



UNIVERSITY
OF
JOHANNESBURG

PROGRAM

: NATIONAL DIPLOMA
ENGINEERING METALLURGY

SUBJECT

: **QUALITY CONTROL II**

CODE

: **TKU21-1**

DATE

: SUPPLEMENTARY EXAM
18 JULY 2014

DURATION

: (Y-PAPER) 08:00 – 11:00

WEIGHT

: 40 : 60

FULL MARKS

: 91

TOTAL MARKS

: 90

EXAMINER

: Dr S C DU PLESSIS

MODERATOR

: Dr S BHERO

NUMBER OF PAGES

: 6 pages plus 8 Annexures

INSTRUCTIONS
PERMITTED (ONLY

: CALCULATORS ARE

ONE PER STUDENT

REQUIREMENTS

: GRAPH PAPER

INSTRUCTIONS TO STUDENTS

ANSWER ALL QUESTIONS

1. Question 1 (11)

The following values are the number of people buying computers from a particular electronics shop per day over a two-week period:

13, 14, 17, 17, 24, 26, 28, 29, 29, 31, 32

1.1 Calculate the mean (2)

1.2 Find the median (3)

1.3 Calculate the mode (1)

1.4 Calculate the variance (5)

Question 2. (18)

The following is the distribution of the monthly bills for 100 accounts at an engineering firm.

Amounts in Rands	Frequency
0 - < 20	11
20 - < 40	23
40 - < 60	33
60 - < 80	18
80 - < 100	10
100 - < 120	5

2.1 Calculate the average (3)

2.2 Find the median (3)

2.3 Calculate the standard deviation (5)

2.4 Find the mode (3)

2.5 Calculate the coefficient of skeweness (4)

Question 3 (7)

The following table shows the 139 employees of a small manufacturing company cross-classified on the basis of gender and work category.

Gender	Work category		
	Production	Sales	Office
Male	75	5	15
Female	25	10	9

Using the given table, answer the next 4 questions: What is the probability of an employee selected at random being:

3.1 A male? (2)

3.2 A female or an office worker? (3)

3.3 A production workers and female? (2)

Question 4 (7)

During the delivery of a box of delicate parts, it can be expected that 10 % break.

A random sample of 8 parts is selected.

4.1 What is the probability that the sample will contain no broken parts? (3)

4.2 What is the probability that the sample will contain one broken part? (4)

Question 5 (7)

Based on past experience, it is assumed that the number of flaws in rolls of grade

Two papers occur with an average of one flaw per five meter of paper.

5.1 What is the probability that there will be exactly three flaws per five meter of paper? (3)

5.2 What is the probability that there will be three or four flaws per 10 meter of paper? (4)

Question 6 (7)

A certain component of an electronic testing device has a service life that can be represented by a normal distribution with mean of 100 hours and a standard deviation of 20 hours.

6.1 Determine the probability that the service life is between 80 hours and 110 hours (4)

6.2 More than 110 hours (3)

Question 7. (6)

Determine the process capability based on the following range values for 20 subgroups of size five. The range values are given as follows:

5 5 7 7 9 11 10 5 7 8 10 12 8 9

Question 8 (8)

For a consumer's risk of 0,10 % and a LQ of 6,5 %, determine the sampling plans for $C=2, 3, 8$, and 12.

Question 9 (11)

Determine the trial central line and the control limits of the control chart for the average and the range for a certain dimension part measured in millimetres. assumed that any out of control points have assignable causes. The measurement are summarised as follows:

Subgroup Number	Measurements				
	A	B	C	D	E
1	22	24	26	28	25
2	32	48	47	53	56
3	45	49	53	66	50
4	56	55	68	77	80
5	30	33	36	39	45
6	78	72	69	63	62
7	55	59	62	57	49
8	71	78	87	65	62
9	63	55	76	73	57
10	71	78	75	71	81
11	46	39	43	39	73
12	39	42	39	38	43
13	52	51	55	57	58

Question 10

(9)

Determine the trial central line and the control limits for each subgroup. Assume that Any out of control points have assignable causes and determine the standard value for the fraction nonconforming for the next production period. The inspection result are given by ;

Date	Number inspected	Number of nonconforming
April 7	100	4
8	100	2
9	100	5
10	100	3
11	100	6
12	100	4
13	100	3
14	100	9
15	100	5
16	100	6
17	100	9
18	100	3
19	100	3
20	100	4
21	100	2
22	100	5
23	100	3
24	100	1
25	100	4
26	100	3

APPENDIX

Table A	Areas Under the Normal Curve
Table B	Factors for Computing Central Lines and 3σ Control Limits for $\bar{X}$, s , and R charts
Table C	The Poisson Distribution
Table D	Random Numbers
Table E	Commonly Used Conversion Factors

Table F	Critical Values of t Distribution
Table G-1	Critical Values of F Distribution ($\alpha = 0.1$)
Table G-2	Critical Values of F Distribution ($\alpha = 0.05$)
Table G-3	Critical Values of F Distribution ($\alpha = 0.01$)
Table H	Orthogonal Arrays

TABLE A Areas Under the Normal Curve^a

$\frac{X_i - \mu}{\sigma}$	0.09	0.08	0.07	0.06	0.05	0.04	0.03	0.02	0.01	0.00
-3.5	0.00017	0.00017	0.00018	0.00019	0.00019	0.00020	0.00021	0.00022	0.00022	0.00023
-3.4	0.00024	0.00025	0.00026	0.00027	0.00028	0.00029	0.00030	0.00031	0.00033	0.00034
-3.3	0.00035	0.00036	0.00038	0.00039	0.00040	0.00042	0.00043	0.00045	0.00047	0.00048
-3.2	0.00050	0.00052	0.00054	0.00056	0.00058	0.00060	0.00062	0.00064	0.00066	0.00069
-3.1	0.00071	0.00074	0.00076	0.00079	0.00082	0.00085	0.00087	0.00090	0.00094	0.00097
-3.0	0.00100	0.00104	0.00107	0.00111	0.00114	0.00118	0.00122	0.00126	0.00131	0.00135
-2.9	0.0014	0.0014	0.0015	0.0015	0.0016	0.0016	0.0017	0.0017	0.0018	0.0019
-2.8	0.0019	0.0020	0.0021	0.0021	0.0022	0.0023	0.0023	0.0024	0.0025	0.0026
-2.7	0.0026	0.0027	0.0028	0.0029	0.0030	0.0031	0.0032	0.0033	0.0034	0.0035
-2.6	0.0036	0.0037	0.0038	0.0039	0.0040	0.0041	0.0043	0.0044	0.0045	0.0047
-2.5	0.0048	0.0049	0.0051	0.0052	0.0054	0.0055	0.0057	0.0059	0.0060	0.0062
-2.4	0.0064	0.0066	0.0068	0.0069	0.0071	0.0073	0.0075	0.0078	0.0080	0.0082
-2.3	0.0084	0.0087	0.0089	0.0091	0.0094	0.0096	0.0099	0.0102	0.0104	0.0107
-2.2	0.0110	0.0113	0.0116	0.0119	0.0122	0.0125	0.0129	0.0132	0.0136	0.0139
-2.1	0.0143	0.0146	0.0150	0.0154	0.0158	0.0162	0.0166	0.0170	0.0174	0.0179
-2.0	0.0183	0.0188	0.0192	0.0197	0.0202	0.0207	0.0212	0.0217	0.0222	0.0228
-1.9	0.0233	0.0239	0.0244	0.0250	0.0256	0.0262	0.0268	0.0274	0.0281	0.0287
-1.8	0.0294	0.0301	0.0307	0.0314	0.0322	0.0329	0.0336	0.0344	0.0351	0.0359
-1.7	0.0367	0.0375	0.0384	0.0392	0.0401	0.0409	0.0418	0.0427	0.0436	0.0446
-1.6	0.0455	0.0465	0.0475	0.0485	0.0495	0.0505	0.0516	0.0526	0.0537	0.0548
-1.5	0.0559	0.0571	0.0582	0.0594	0.0606	0.0618	0.0630	0.0643	0.0655	0.0668
-1.4	0.0681	0.0694	0.0708	0.0721	0.0735	0.0749	0.0764	0.0778	0.0793	0.0808
-1.3	0.0823	0.0838	0.0853	0.0869	0.0885	0.0901	0.0918	0.0934	0.0951	0.0968
-1.2	0.0895	0.1003	0.1020	0.1038	0.1057	0.1075	0.1093	0.1112	0.1131	0.1151
-1.1	0.1170	0.1190	0.1210	0.1230	0.1251	0.1271	0.1292	0.1314	0.1335	0.1357
-1.0	0.1379	0.1401	0.1423	0.1446	0.1469	0.1492	0.1515	0.1539	0.1562	0.1587
-0.9	0.1611	0.1635	0.1660	0.1685	0.1711	0.1736	0.1762	0.1788	0.1814	0.1841
-0.8	0.1867	0.1894	0.1922	0.1949	0.1977	0.2005	0.2033	0.2061	0.2090	0.2119
-0.7	0.2148	0.2177	0.2207	0.2236	0.2266	0.2297	0.2327	0.2358	0.2389	0.2420
-0.6	0.2451	0.2483	0.2514	0.2546	0.2578	0.2611	0.2643	0.2676	0.2709	0.2743
-0.5	0.2776	0.2810	0.2843	0.2877	0.2912	0.2946	0.2981	0.3015	0.3050	0.3085

TABLE A (Continued)

$\frac{X_i - \mu}{\sigma}$	0.09	0.08	0.07	0.06	0.05	0.04	0.03	0.02	0.01	0.00
-0.4	0.3121	0.3156	0.3192	0.3228	0.3264	0.3300	0.3336	0.3372	0.3409	0.3446
-0.3	0.3483	0.3520	0.3557	0.3594	0.3632	0.3669	0.3707	0.3745	0.3783	0.3821
-0.2	0.3859	0.3897	0.3936	0.3974	0.4013	0.4052	0.4090	0.4129	0.4168	0.4207
-0.1	0.4247	0.4286	0.4325	0.4364	0.4404	0.4443	0.4483	0.4522	0.4562	0.4602
-0.0	0.4641	0.4681	0.4721	0.4761	0.4801	0.4840	0.4880	0.4920	0.4960	0.5000
$\frac{X_i - \mu}{\sigma}$	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
+0.0	0.5000	0.5040	0.5080	0.5120	0.5160	0.5199	0.5239	0.5279	0.5319	0.5359
+0.1	0.5398	0.5438	0.5478	0.5517	0.5557	0.5596	0.5636	0.5675	0.5714	0.5753
+0.2	0.5793	0.5832	0.5871	0.5910	0.5948	0.5987	0.6026	0.6064	0.6103	0.6141
+0.3	0.6179	0.6217	0.6255	0.6293	0.6331	0.6368	0.6406	0.6443	0.6480	0.6517
+0.4	0.6554	0.6591	0.6628	0.6664	0.6700	0.6736	0.6772	0.6808	0.6844	0.6879
+0.5	0.6915	0.6950	0.6985	0.7019	0.7054	0.7088	0.7123	0.7157	0.7190	0.7224
+0.6	0.7257	0.7291	0.7324	0.7357	0.7389	0.7422	0.7454	0.7486	0.7517	0.7549
+0.7	0.7580	0.7611	0.7642	0.7673	0.7704	0.7734	0.7764	0.7794	0.7823	0.7852
+0.8	0.7881	0.7910	0.7939	0.7967	0.7995	0.8023	0.8051	0.8079	0.8106	0.8133
+0.9	0.8159	0.8186	0.8212	0.8238	0.8264	0.8289	0.8315	0.8340	0.8365	0.8389
+1.0	0.8413	0.8438	0.8461	0.8485	0.8508	0.8531	0.8554	0.8577	0.8599	0.8621
+1.1	0.8643	0.8665	0.8686	0.8708	0.8729	0.8749	0.8770	0.8790	0.8810	0.8830
+1.2	0.8849	0.8869	0.8888	0.8907	0.8925	0.8944	0.8962	0.8980	0.8997	0.9015
+1.3	0.9032	0.9049	0.9066	0.9082	0.9099	0.9115	0.9131	0.9147	0.9162	0.9177
+1.4	0.9192	0.9207	0.9222	0.9236	0.9251	0.9265	0.9279	0.9292	0.9306	0.9319
+1.5	0.9332	0.9345	0.9357	0.9370	0.9382	0.9394	0.9406	0.9418	0.9429	0.9441
+1.6	0.9452	0.9463	0.9474	0.9484	0.9495	0.9505	0.9515	0.9525	0.9535	0.9545
+1.7	0.9554	0.9564	0.9573	0.9582	0.9591	0.9599	0.9608	0.9616	0.9625	0.9633
+1.8	0.9641	0.9649	0.9656	0.9664	0.9671	0.9678	0.9686	0.9693	0.9699	0.9706
+1.9	0.9713	0.9719	0.9726	0.9732	0.9738	0.9744	0.9750	0.9756	0.9761	0.9767
+2.0	0.9773	0.9778	0.9783	0.9788	0.9793	0.9798	0.9803	0.9808	0.9812	0.9817
+2.1	0.9821	0.9826	0.9830	0.9834	0.9838	0.9842	0.9846	0.9850	0.9854	0.9857
+2.2	0.9861	0.9864	0.9868	0.9871	0.9875	0.9878	0.9881	0.9884	0.9887	0.9890
+2.3	0.9893	0.9896	0.9898	0.9901	0.9904	0.9906	0.9909	0.9911	0.9913	0.9916
+2.4	0.9918	0.9920	0.9922	0.9925	0.9927	0.9929	0.9931	0.9932	0.9934	0.9936
+2.5	0.9938	0.9940	0.9941	0.9943	0.9945	0.9946	0.9948	0.9949	0.9951	0.9952
+2.6	0.9953	0.9955	0.9956	0.9957	0.9959	0.9960	0.9961	0.9962	0.9963	0.9964
+2.7	0.9965	0.9966	0.9967	0.9968	0.9969	0.9970	0.9971	0.9972	0.9973	0.9974
+2.8	0.9974	0.9975	0.9976	0.9977	0.9977	0.9978	0.9979	0.9979	0.9980	0.9981
+2.9	0.9981	0.9982	0.9983	0.9983	0.9984	0.9984	0.9985	0.9985	0.9986	0.9986
+3.0	0.99865	0.99869	0.99874	0.99878	0.99882	0.99886	0.99889	0.99893	0.99896	0.99900
+3.1	0.99903	0.99906	0.99910	0.99913	0.99915	0.99918	0.99921	0.99924	0.99926	0.99929
+3.2	0.99931	0.99934	0.99936	0.99938	0.99940	0.99942	0.99944	0.99946	0.99948	0.99950
+3.3	0.99952	0.99953	0.99955	0.99957	0.99958	0.99960	0.99961	0.99962	0.99964	0.99965
+3.4	0.99966	0.99967	0.99969	0.99970	0.99971	0.99972	0.99973	0.99974	0.99975	0.99976
+3.5	0.99977	0.99978	0.99978	0.99979	0.99980	0.99981	0.99981	0.99982	0.99983	0.99983

*Proportion of total area under the curve that is under the proportion of the curve from $-\infty$ to $(X_i - \mu)/\sigma$ (X_i represents any desired value of the variable X)

TABLE B Factors for Computing Central Limits and 3σ Control Limits for $\bar{X}$, s , and R Charts

Observations in Sample, n	CHART FOR AVERAGES					CHART FOR STANDARD DEVIATIONS										CHART FOR RANGES				
	Factors for Control Limits					Factor for Central Line					Factors for Control Limits					Factor for Central Line				
	Factors for Control Limits					Factor for Central Line					Factors for Control Limits					Factor for Central Line				
	A	A_2	A_3	c_4	B_3	B_4	B_5	B_6	d_3	d_4	D_1	D_2	D_3	D_4	d_3	d_4	D_1	D_2	D_3	D_4
2	2.121	1.880	2.659	0.7979	0	3.267	0	2.606	1.128	0.853	0	3.686	0	3.267	0.853	1.128	0	3.686	0	3.267
3	1.732	1.023	1.954	0.8862	0	2.568	0	2.276	1.693	0.888	0	4.358	0	2.574	0.888	1.693	0	4.358	0	2.574
4	1.500	0.729	1.628	0.9213	0	2.266	0	2.088	2.059	0.880	0	4.698	0	2.282	0.880	2.059	0	4.698	0	2.282
5	1.342	0.577	1.427	0.9400	0	2.089	0	1.964	2.326	0.864	0	4.918	0	2.114	0.864	2.326	0	4.918	0	2.114
6	1.225	0.483	1.287	0.9515	0.030	1.970	0.029	1.874	2.534	0.848	0	5.078	0	2.004	0.848	2.534	0	5.078	0	2.004
7	1.134	0.419	1.182	0.9594	0.118	1.882	0.113	1.806	2.704	0.833	0.204	5.204	0.076	1.924	0.833	2.704	0.204	5.204	0.076	1.924
8	1.061	0.373	1.099	0.9650	0.185	1.815	0.179	1.751	2.847	0.820	0.388	5.306	0.136	1.864	0.820	2.847	0.388	5.306	0.136	1.864
9	1.000	0.337	1.032	0.9693	0.239	1.761	0.232	1.707	2.970	0.808	0.547	5.393	0.184	1.816	0.808	2.970	0.547	5.393	0.184	1.816
10	0.949	0.308	0.975	0.9727	0.284	1.716	0.276	1.669	3.078	0.797	0.687	5.469	0.223	1.777	0.797	3.078	0.687	5.469	0.223	1.777
11	0.905	0.285	0.927	0.9754	0.321	1.679	0.313	1.637	3.173	0.787	0.811	5.535	0.256	1.744	0.787	3.173	0.811	5.535	0.256	1.744
12	0.866	0.266	0.886	0.9776	0.354	1.646	0.346	1.610	3.258	0.778	0.922	5.594	0.283	1.717	0.778	3.258	0.922	5.594	0.283	1.717
13	0.832	0.249	0.850	0.9794	0.382	1.618	0.374	1.585	3.336	0.770	1.025	5.647	0.307	1.693	0.770	3.336	1.025	5.647	0.307	1.693
14	0.802	0.235	0.817	0.9810	0.406	1.594	0.399	1.563	3.407	0.763	1.118	5.696	0.328	1.672	0.763	3.407	1.118	5.696	0.328	1.672
15	0.775	0.223	0.789	0.9823	0.428	1.572	0.421	1.544	3.472	0.756	1.203	5.741	0.347	1.653	0.756	3.472	1.203	5.741	0.347	1.653
16	0.750	0.212	0.763	0.9835	0.448	1.552	0.440	1.526	3.532	0.750	1.282	5.782	0.363	1.637	0.750	3.532	1.282	5.782	0.363	1.637
17	0.728	0.203	0.739	0.9845	0.466	1.534	0.458	1.511	3.588	0.744	1.356	5.820	0.378	1.622	0.744	3.588	1.356	5.820	0.378	1.622
18	0.707	0.194	0.718	0.9854	0.482	1.518	0.475	1.496	3.640	0.739	1.424	5.856	0.391	1.608	0.739	3.640	1.424	5.856	0.391	1.608
19	0.688	0.187	0.698	0.9862	0.497	1.503	0.490	1.483	3.689	0.734	1.487	5.891	0.403	1.597	0.734	3.689	1.487	5.891	0.403	1.597
20	0.671	0.180	0.680	0.9869	0.510	1.490	0.504	1.470	3.735	0.729	1.549	5.921	0.415	1.585	0.729	3.735	1.549	5.921	0.415	1.585

Copyright ASTM, 100 Barr Harbor Drive, West Conshohocken, PA, 19428

1.2%, the OC
obtained. Each

TABLE 9-4 np Values for Corresponding c Values and Typical Producer's and Consumer's Risks

c	$P_a = 0.99$ ($\alpha = 0.01$)	$P_a = 0.95$ ($\alpha = 0.05$)	$P_a = 0.90$ ($\alpha = 0.10$)	$P_a = 0.10$ ($\beta = 0.10$)	$P_a = 0.05$ ($\beta = 0.05$)	$P_a = 0.01$ ($\beta = 0.01$)	RATIO OF $P_{0.10}/P_{0.95}$
0	0.010	0.051	0.105	2.303	2.996	4.605	44.890
1	0.149	0.355	0.532	3.890	4.744	6.638	10.946
2	0.436	0.818	1.102	5.322	6.296	8.406	6.509
3	0.823	1.366	1.745	6.681	7.754	10.045	4.890
4	1.279	1.970	2.433	7.994	9.154	11.605	4.057
5	1.785	2.613	3.152	9.275	10.513	13.108	3.549
6	2.330	3.286	3.895	10.532	11.842	14.571	3.206
7	2.906	3.981	4.656	11.771	13.148	16.000	2.957
8	3.507	4.695	5.432	12.995	14.434	17.403	2.768
9	4.130	5.426	6.221	14.206	15.705	18.783	2.618
10	4.771	6.169	7.021	15.407	16.962	20.145	2.497
11	5.428	6.924	7.829	16.598	18.208	21.490	2.397
12	6.099	7.690	8.646	17.782	19.442	22.821	2.312
13	6.782	8.464	9.470	18.958	20.668	24.139	2.240
14	7.477	9.246	10.300	20.128	21.886	25.446	2.177
15	8.181	10.035	11.135	21.292	23.098	26.743	2.122

Source: Extracted by permission from J. M. Cameron, "Tables for Constructing and for Computing the Operating Characteristics of Single-Sampling Plans," *Industry Quality Control*, Vol. 9, No. 1 (July 1952): 39.

nd AQL.

TABLE C The Poisson Distribution $P(c) = \frac{(np_0)^c}{c!} e^{-np_0}$ (Cumulative Values Are in Parentheses)

c np_0	0.1	0.2	0.3	0.4	0.5
0	0.905 (0.905)	0.819 (0.819)	0.741 (0.741)	0.670 (0.670)	0.607 (0.607)
1	0.091 (0.996)	0.164 (0.983)	0.222 (0.963)	0.268 (0.938)	0.303 (0.910)
2	0.004 (1.000)	0.016 (0.999)	0.033 (0.996)	0.054 (0.992)	0.076 (0.986)
3		0.010 (1.000)	0.004 (1.000)	0.007 (0.999)	0.013 (0.999)
4		0.001 (1.000)	0.001 (1.000)		
c np_0	0.6	0.7	0.8	0.9	1.0
0	0.549 (0.549)	0.497 (0.497)	0.449 (0.449)	0.406 (0.406)	0.368 (0.368)
1	0.329 (0.878)	0.349 (0.845)	0.359 (0.808)	0.366 (0.772)	0.368 (0.736)
2	0.099 (0.977)	0.122 (0.967)	0.144 (0.952)	0.166 (0.938)	0.184 (0.920)
3	0.020 (0.997)	0.028 (0.995)	0.039 (0.991)	0.049 (0.987)	0.061 (0.981)
4	0.003 (1.000)	0.005 (1.000)	0.008 (0.999)	0.011 (0.998)	0.016 (0.997)
5			0.001 (1.000)	0.002 (1.000)	0.003 (1.000)
c np_0	1.1	1.2	1.3	1.4	1.5
0	0.333 (0.333)	0.301 (0.301)	0.273 (0.273)	0.247 (0.247)	0.223 (0.223)
1	0.366 (0.699)	0.361 (0.662)	0.354 (0.627)	0.345 (0.592)	0.335 (0.558)
2	0.201 (0.900)	0.217 (0.879)	0.230 (0.857)	0.242 (0.834)	0.251 (0.809)
3	0.074 (0.974)	0.087 (0.966)	0.100 (0.957)	0.113 (0.947)	0.126 (0.935)
4	0.021 (0.995)	0.026 (0.992)	0.032 (0.989)	0.039 (0.986)	0.047 (0.982)
5	0.004 (0.999)	0.007 (0.999)	0.009 (0.998)	0.011 (0.997)	0.014 (0.996)
6	0.001 (1.000)	0.001 (1.000)	0.002 (1.000)	0.003 (1.000)	0.004 (1.000)
c np_0	1.6	1.7	1.8	1.9	2.0
0	0.202 (0.202)	0.183 (0.183)	0.165 (0.165)	0.150 (0.150)	0.135 (0.135)
1	0.323 (0.525)	0.311 (0.494)	0.298 (0.463)	0.284 (0.434)	0.271 (0.406)
2	0.258 (0.783)	0.264 (0.758)	0.268 (0.731)	0.270 (0.704)	0.271 (0.677)
3	0.138 (0.921)	0.149 (0.907)	0.161 (0.892)	0.171 (0.875)	0.180 (0.857)
4	0.055 (0.976)	0.064 (0.971)	0.072 (0.964)	0.081 (0.956)	0.090 (0.947)
5	0.018 (0.994)	0.022 (0.993)	0.026 (0.990)	0.031 (0.987)	0.036 (0.983)
6	0.005 (0.999)	0.006 (0.999)	0.008 (0.998)	0.010 (0.997)	0.012 (0.995)
7	0.001 (1.000)	0.001 (1.000)	0.002 (1.000)	0.003 (1.000)	0.004 (0.999)
8					0.001 (1.000)
c np_0	2.1	2.2	2.3	2.4	2.5
0	0.123 (0.123)	0.111 (0.111)	0.100 (0.100)	0.091 (0.091)	0.082 (0.082)
1	0.257 (0.380)	0.244 (0.355)	0.231 (0.331)	0.218 (0.309)	0.205 (0.287)
2	0.270 (0.650)	0.268 (0.623)	0.265 (0.596)	0.261 (0.570)	0.256 (0.543)
3	0.189 (0.839)	0.197 (0.820)	0.203 (0.799)	0.209 (0.779)	0.214 (0.757)
4	0.099 (0.938)	0.108 (0.928)	0.117 (0.916)	0.125 (0.904)	0.134 (0.891)
5	0.042 (0.980)	0.048 (0.976)	0.054 (0.970)	0.060 (0.964)	0.067 (0.958)
6	0.015 (0.995)	0.017 (0.993)	0.021 (0.991)	0.024 (0.988)	0.028 (0.986)
7	0.004 (0.999)	0.005 (0.998)	0.007 (0.998)	0.008 (0.996)	0.010 (0.996)
8	0.001 (1.000)	0.002 (1.000)	0.002 (1.000)	0.003 (0.999)	0.003 (0.999)
9				0.001 (1.000)	0.001 (1.000)

TABLE C (Continued)

$c \cdot np_0$	2.6	2.7	2.8	2.9	3.0
0	0.074 (0.074)	0.067 (0.067)	0.061 (0.061)	0.055 (0.055)	0.050 (0.050)
1	0.193 (0.267)	0.182 (0.249)	0.170 (0.231)	0.160 (0.215)	0.149 (0.199)
2	0.251 (0.518)	0.245 (0.494)	0.238 (0.469)	0.231 (0.446)	0.224 (0.423)
3	0.218 (0.736)	0.221 (0.715)	0.223 (0.692)	0.224 (0.670)	0.224 (0.647)
4	0.141 (0.877)	0.149 (0.864)	0.156 (0.848)	0.162 (0.832)	0.168 (0.815)
5	0.074 (0.951)	0.080 (0.944)	0.087 (0.935)	0.094 (0.926)	0.101 (0.916)
6	0.032 (0.983)	0.036 (0.980)	0.041 (0.976)	0.045 (0.971)	0.050 (0.966)
7	0.012 (0.995)	0.014 (0.994)	0.016 (0.992)	0.019 (0.990)	0.022 (0.988)
8	0.004 (0.999)	0.005 (0.999)	0.006 (0.998)	0.007 (0.997)	0.008 (0.996)
9	0.001 (1.000)	0.001 (1.000)	0.002 (1.000)	0.002 (0.999)	0.003 (0.999)
10				0.001 (1.000)	0.001 (1.000)
$c \cdot np_0$	3.1	3.2	3.3	3.4	3.5
0	0.045 (0.045)	0.041 (0.041)	0.037 (0.037)	0.033 (0.033)	0.030 (0.030)
1	0.140 (0.185)	0.130 (0.171)	0.122 (0.159)	0.113 (0.146)	0.106 (0.136)
2	0.216 (0.401)	0.209 (0.380)	0.201 (0.360)	0.193 (0.339)	0.185 (0.321)
3	0.224 (0.625)	0.223 (0.603)	0.222 (0.582)	0.219 (0.558)	0.216 (0.537)
4	0.173 (0.798)	0.178 (0.781)	0.182 (0.764)	0.186 (0.744)	0.189 (0.726)
5	0.107 (0.905)	0.114 (0.895)	0.120 (0.884)	0.126 (0.870)	0.132 (0.858)
6	0.056 (0.961)	0.061 (0.956)	0.066 (0.950)	0.071 (0.941)	0.077 (0.935)
7	0.025 (0.986)	0.028 (0.984)	0.031 (0.981)	0.035 (0.976)	0.038 (0.973)
8	0.010 (0.996)	0.011 (0.995)	0.012 (0.993)	0.015 (0.991)	0.017 (0.990)
9	0.003 (0.999)	0.004 (0.999)	0.005 (0.998)	0.006 (0.997)	0.007 (0.997)
10	0.001 (1.000)	0.001 (1.000)	0.002 (1.000)	0.002 (0.999)	0.002 (0.999)
11				0.001 (1.000)	0.001 (1.000)
$c \cdot np_0$	3.6	3.7	3.8	3.9	4.0
0	0.027 (0.027)	0.025 (0.025)	0.022 (0.022)	0.020 (0.020)	0.018 (0.018)
1	0.098 (0.125)	0.091 (0.116)	0.085 (0.107)	0.079 (0.099)	0.073 (0.091)
2	0.177 (0.302)	0.169 (0.285)	0.161 (0.268)	0.154 (0.253)	0.147 (0.238)
3	0.213 (0.515)	0.209 (0.494)	0.205 (0.473)	0.200 (0.453)	0.195 (0.433)
4	0.191 (0.706)	0.193 (0.687)	0.194 (0.667)	0.195 (0.648)	0.195 (0.628)
5	0.138 (0.844)	0.143 (0.830)	0.148 (0.815)	0.152 (0.800)	0.157 (0.785)
6	0.083 (0.927)	0.088 (0.918)	0.094 (0.909)	0.099 (0.899)	0.104 (0.889)
7	0.042 (0.969)	0.047 (0.965)	0.051 (0.960)	0.055 (0.954)	0.060 (0.949)
8	0.019 (0.988)	0.022 (0.987)	0.024 (0.984)	0.027 (0.981)	0.030 (0.979)
9	0.008 (0.996)	0.009 (0.996)	0.010 (0.994)	0.012 (0.993)	0.013 (0.992)
10	0.003 (0.999)	0.003 (0.999)	0.004 (0.998)	0.004 (0.997)	0.005 (0.997)
11	0.001 (1.000)	0.001 (1.000)	0.001 (0.999)	0.002 (0.999)	0.002 (0.999)
12			0.001 (1.000)	0.001 (1.000)	0.001 (1.000)
$c \cdot np_0$	4.1	4.2	4.3	4.4	4.5
0	0.017 (0.017)	0.015 (0.015)	0.014 (0.014)	0.012 (0.012)	0.011 (0.011)
1	0.068 (0.085)	0.063 (0.078)	0.058 (0.072)	0.054 (0.066)	0.050 (0.061)
2	0.139 (0.224)	0.132 (0.210)	0.126 (0.198)	0.119 (0.185)	0.113 (0.174)
3	0.190 (0.414)	0.185 (0.395)	0.180 (0.378)	0.174 (0.359)	0.169 (0.343)
4	0.195 (0.609)	0.195 (0.590)	0.193 (0.571)	0.192 (0.551)	0.190 (0.533)

(Continued)

TABLE C (Continued)

$c n p_0$	4.1	4.2	4.3	4.4	4.5
5	0.160 (0.769)	0.163 (0.753)	0.166 (0.737)	0.169 (0.720)	0.171 (0.704)
6	0.110 (0.879)	0.114 (0.867)	0.119 (0.856)	0.124 (0.844)	0.128 (0.832)
7	0.064 (0.943)	0.069 (0.936)	0.073 (0.929)	0.078 (0.922)	0.082 (0.914)
8	0.033 (0.976)	0.036 (0.972)	0.040 (0.969)	0.043 (0.965)	0.046 (0.960)
9	0.015 (0.991)	0.017 (0.989)	0.019 (0.988)	0.021 (0.986)	0.023 (0.983)
10	0.006 (0.997)	0.007 (0.996)	0.008 (0.996)	0.009 (0.995)	0.011 (0.994)
11	0.002 (0.999)	0.003 (0.999)	0.003 (0.999)	0.004 (0.999)	0.004 (0.998)
12	0.001 (1.000)	0.001 (1.000)	0.001 (1.000)	0.001 (1.000)	0.001 (0.999)
13					0.001 (1.000)
$c n p_0$	4.6	4.7	4.8	4.9	5.0
0	0.010 (0.010)	0.009 (0.009)	0.008 (0.008)	0.008 (0.008)	0.007 (0.007)
1	0.046 (0.056)	0.043 (0.052)	0.039 (0.047)	0.037 (0.045)	0.034 (0.041)
2	0.106 (0.162)	0.101 (0.153)	0.095 (0.142)	0.090 (0.135)	0.084 (0.125)
3	0.163 (0.325)	0.157 (0.310)	0.152 (0.294)	0.146 (0.281)	0.140 (0.265)
4	0.188 (0.513)	0.185 (0.495)	0.182 (0.476)	0.179 (0.460)	0.176 (0.441)
5	0.172 (0.685)	0.174 (0.669)	0.175 (0.651)	0.175 (0.635)	0.176 (0.617)
6	0.132 (0.817)	0.136 (0.805)	0.140 (0.791)	0.143 (0.778)	0.146 (0.763)
7	0.087 (0.904)	0.091 (0.896)	0.096 (0.887)	0.100 (0.878)	0.105 (0.868)
8	0.050 (0.954)	0.054 (0.950)	0.058 (0.945)	0.061 (0.939)	0.065 (0.933)
9	0.026 (0.980)	0.028 (0.978)	0.031 (0.976)	0.034 (0.973)	0.036 (0.969)
10	0.012 (0.992)	0.013 (0.991)	0.015 (0.991)	0.016 (0.989)	0.018 (0.987)
11	0.005 (0.997)	0.006 (0.997)	0.006 (0.997)	0.007 (0.996)	0.008 (0.995)
12	0.002 (0.999)	0.002 (0.999)	0.002 (0.999)	0.003 (0.999)	0.003 (0.998)
13	0.001 (1.000)	0.001 (1.000)	0.001 (1.000)	0.001 (1.000)	0.001 (0.999)
14					0.001 (1.000)
$c n p_0$	5.0	7.0	8.0	9.0	10.0
0	0.002 (0.002)	0.001 (0.001)	0.000 (0.000)	0.000 (0.000)	0.000 (0.000)
1	0.015 (0.017)	0.006 (0.007)	0.003 (0.003)	0.001 (0.001)	0.000 (0.000)
2	0.045 (0.062)	0.022 (0.029)	0.011 (0.014)	0.005 (0.006)	0.002 (0.002)
3	0.089 (0.151)	0.052 (0.081)	0.029 (0.043)	0.015 (0.021)	0.007 (0.009)
4	0.134 (0.285)	0.091 (0.172)	0.057 (0.100)	0.034 (0.055)	0.019 (0.028)
5	0.161 (0.446)	0.128 (0.300)	0.092 (0.192)	0.061 (0.116)	0.038 (0.066)
6	0.161 (0.607)	0.149 (0.449)	0.122 (0.314)	0.091 (0.091)	0.063 (0.129)
7	0.138 (0.745)	0.149 (0.598)	0.140 (0.454)	0.117 (0.324)	0.090 (0.219)
8	0.103 (0.848)	0.131 (0.729)	0.140 (0.594)	0.132 (0.456)	0.113 (0.332)
9	0.069 (0.917)	0.102 (0.831)	0.124 (0.718)	0.132 (0.588)	0.124 (0.457)
10	0.041 (0.958)	0.071 (0.902)	0.099 (0.817)	0.119 (0.707)	0.125 (0.582)
11	0.023 (0.981)	0.045 (0.947)	0.072 (0.889)	0.097 (0.804)	0.114 (0.696)
12	0.011 (0.992)	0.026 (0.973)	0.048 (0.937)	0.073 (0.877)	0.095 (0.791)
13	0.005 (0.997)	0.014 (0.987)	0.030 (0.967)	0.050 (0.927)	0.073 (0.864)
14	0.002 (0.999)	0.007 (0.994)	0.017 (0.984)	0.032 (0.959)	0.052 (0.916)
15	0.001 (1.000)	0.003 (0.997)	0.009 (0.993)	0.019 (0.978)	0.035 (0.951)
16		0.002 (0.999)	0.004 (0.997)	0.011 (0.989)	0.022 (0.973)
17		0.001 (1.000)	0.002 (0.999)	0.006 (0.995)	0.013 (0.986)

TABLE C (Continued)

c/p_0	6.0	7.0	8.0	9.0	10.0
18			0.001 (1.000)	0.003 (0.998)	0.007 (0.993)
19				0.001 (0.999)	0.004 (0.997)
20				0.001 (1.000)	0.002 (0.999)
21					0.001 (1.000)
c/p_0	11.0	12.0	13.0	14.0	15.0
0	0.000 (0.000)	0.000 (0.000)	0.000 (0.000)	0.000 (0.000)	0.000 (0.000)
1	0.000 (0.000)	0.000 (0.000)	0.000 (0.000)	0.000 (0.000)	0.000 (0.000)
2	0.001 (0.001)	0.000 (0.000)	0.000 (0.000)	0.000 (0.000)	0.000 (0.000)
3	0.004 (0.005)	0.002 (0.002)	0.001 (0.001)	0.000 (0.000)	0.000 (0.000)
4	0.010 (0.015)	0.005 (0.007)	0.003 (0.004)	0.001 (0.001)	0.001 (0.001)
5	0.022 (0.037)	0.013 (0.020)	0.007 (0.011)	0.004 (0.005)	0.002 (0.003)
6	0.041 (0.078)	0.025 (0.045)	0.015 (0.026)	0.009 (0.014)	0.005 (0.008)
7	0.065 (0.143)	0.044 (0.089)	0.028 (0.054)	0.017 (0.031)	0.010 (0.018)
8	0.089 (0.232)	0.066 (0.155)	0.046 (0.100)	0.031 (0.062)	0.019 (0.037)
9	0.109 (0.341)	0.087 (0.242)	0.066 (0.166)	0.047 (0.109)	0.032 (0.069)
10	0.119 (0.460)	0.105 (0.347)	0.086 (0.252)	0.066 (0.175)	0.049 (0.118)
11	0.119 (0.579)	0.114 (0.461)	0.101 (0.353)	0.084 (0.259)	0.066 (0.184)
12	0.109 (0.688)	0.114 (0.575)	0.110 (0.463)	0.099 (0.358)	0.083 (0.267)
13	0.093 (0.781)	0.106 (0.681)	0.110 (0.573)	0.106 (0.464)	0.096 (0.363)
14	0.073 (0.854)	0.091 (0.772)	0.102 (0.675)	0.106 (0.570)	0.102 (0.465)
15	0.053 (0.907)	0.072 (0.844)	0.088 (0.763)	0.099 (0.669)	0.102 (0.567)
16	0.037 (0.944)	0.054 (0.896)	0.072 (0.835)	0.087 (0.756)	0.096 (0.663)
17	0.024 (0.968)	0.038 (0.936)	0.055 (0.890)	0.071 (0.827)	0.085 (0.748)
18	0.015 (0.983)	0.026 (0.962)	0.040 (0.930)	0.056 (0.883)	0.071 (0.819)
19	0.008 (0.991)	0.016 (0.978)	0.027 (0.957)	0.041 (0.924)	0.056 (0.875)
20	0.005 (0.996)	0.010 (0.988)	0.018 (0.975)	0.029 (0.953)	0.042 (0.917)
21	0.002 (0.998)	0.006 (0.994)	0.011 (0.986)	0.019 (0.972)	0.030 (0.947)
22	0.001 (0.999)	0.003 (0.997)	0.006 (0.992)	0.012 (0.984)	0.020 (0.967)
23	0.001 (1.000)	0.002 (0.999)	0.004 (0.996)	0.007 (0.991)	0.013 (0.980)
24		0.001 (1.000)	0.002 (0.998)	0.004 (0.995)	0.008 (0.988)
25			0.001 (0.999)	0.003 (0.998)	0.005 (0.993)
26			0.001 (1.000)	0.001 (0.999)	0.003 (0.996)
27				0.001 (1.000)	0.002 (0.998)
28					0.001 (0.999)
29					0.001 (1.000)

